

Region: 2

Location: NY067

CSS #: 20245

Maximo Work Order No.: 5087

Asset #: NA

Date Issued: 08/01/19

Original Description: Approximately 15' of pipe that includes a trap could not be water jetted (likely due to the pipe collapsing), everything is currently draining properly, but it is recommended this section of pipe be excavated (both inside and outside of building 1) and replaced.

Repairs Needed:

Excavation outside of back of wall between wall and parking lot to expose broken sewer line. Cutting outbad pipe. Installing new pipe and fittings in that area only. Backfilling to existing grade. **Pictures will be taken once pipe is uncovered that is being replaced.**

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
1	NA	Excavation and backfilling to replace broken sewer line.	--	--	\$3,500.00	\$0.00	\$3,500.00
--	NA	RFC Labor 2 men for 1day	16	\$100.00	--	--	\$1,600.00
--	NA	TWI Labor	8	\$100.00	--	--	\$800.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost		Total Cost	CE Factor	Total Estimate
24	\$2,400.00	\$3,500.00		\$5,900.00	90%	\$5,310.00

RFC Contracting Inc
1040 Whitesboro Street
Utica, NY 13502
(315) 723-0225
rfcccontracting1@yahoo.com
<http://www.rfcplumbercontractor.com>



Estimate

ADDRESS	SHIP TO	ESTIMATE #	1685
Tide Water INC. 3761 Attucks Dr Powell, OH 43065	Tide Water INC. 3761 Attucks Dr Powell, OH 43065	DATE	08/01/2019
<hr/>			
ACTIVITY	QTY	RATE	AMOUNT
Location NY067 Reserve Center 95 Burrstone Rd Utica Ny Scope of work- Excavation outside of back of wall between wall and parking lot to expose broken sewer line. Cutting out bad pipe. Installing new pipe and fittings in that area only. Backfilling back to existing grade.			
Services Excavation and backfilling.		3,500.00	
Services Plumbing Labor 2 service men adays labor.		1,600.00	
	TOTAL		\$5,100.00

Accepted By

Accepted Date