

Additional Funding Request

DE007	CSS# 21224 WO# 10631 Asset# NA			
Description of Repairs	Labor and materials needed to replace 3 Sink Faucets.			
Diagnosis: Initial Work Order	There are three sink faucets not working throughout the center. One is located in the ladies restroom on the NG wing, one is located in the 1st floor men's room next to the gym, the last is in the 2nd floor men's room. I'm not sure if it is just batteries or if there is another issue.			
Diagnostic Fee	\$ 160 TW Labor \$80/hr x 2			
Additional Labor Cost to Perform Repairs	\$ 640 TW Labor \$80/hr x 8			
Additional Cost	\$ 1,154.17			
	Faucet #802-V665ABCP	3	\$361.24	\$1,083.73
	Sales Tax	1		\$70.44
Total Cost of Repair	\$ 1,954.17			



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials needed to replace 3 Sink Faucets.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Faucets #802-V665ABCP	3	\$361.24		\$1,083.72
Sales Tax				\$70.44
Diagnostic			2	\$160.00
SUB-TOTAL COSTS:	Materials Total	\$1,154.16	Labor	\$800.00
TOTAL			\$1,954.16	





CHICAGO FAUCETS
Faucet, Metering, Push, 1/2 In.
Male NPSM

Item # **3TFJ1**
Mfr Model # **802-V665ABCP**

ZOOM



Qty

1

Web Price
\$301.06 / each

ADD TO CART

ADD TO LIST

AVAILABILITY

Shipping (Current Location)