

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD002 Date of Visit: 10/02/2020

Contractor Personnel on Site:

- | | |
|-----------------------|----------|
| 1. <u>Brian Davis</u> | 4. _____ |
| 2. <u>Sam Kutz</u> | 5. _____ |
| 3. _____ | 6. _____ |


Service Calls – Service Call Number and Description

1. WO# 11072 CSS:21543
2. Replaced baldor fan motor
3. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: BRIAN DAVIS Date: 10.2.2020

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: _____

E-Mail: _____

Tina Lee

From: Lindsay Ruby <lindsay@sandsmidatlantic.com>
Sent: Tuesday, October 20, 2020 7:55 AM
To: Tina Lee; Adam Colopy
Subject: COW ticket

Follow Up Flag: Follow up
Flag Status: Flagged

Tina,
Attached is the uncomplete COW ticket for MD002 WO# 11072.
As for warranty, Jim's Electric Motor did not give me any documents they said if anything were to happen they would replace it.
Thank you :)

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD002 Date of Visit: 10/02/2020

Contractor Personnel on Site:

- | | |
|-----------------------|----------|
| 1. <u>Brian Davis</u> | 4. _____ |
| 2. <u>Sam Kutz</u> | 5. _____ |
| 3. _____ | 6. _____ |

Service Calls – Service Call Number and Description

- | |
|-------------------------------------|
| 1. <u>WO# 11072 CS:2543</u> |
| 2. <u>Replaced blower fan motor</u> |
| 3. _____ |

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: BRIAN DAVIS Date: 10-2-2020

Signed: [Signature]

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: _____

E-Mail: _____

Lindsay Ruby

S&S Mechanical

"Feeling Good About What We Do"

Phone: 301-574-1555

Fax: 301-574-1558

www.sandsmidatlantic.com

lindsay@sandsmidatlantic.com