



INVOICE

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

Jan 6, 2020

RE:css 22157 ny128

- Remove flush valve and rebuild
- Install rebuild kit and seals
- Install vacuum breaker assembly
- Test for leaks

Total: \$450.00

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL