

Region: 5

Location: VA011

CSS #: 22559

Maximo Work Order No.: 11412

Asset #: NA

Date Issued: 11/18/19

Original Description:

Bill Davis was out for a leak and notice a leak on the pump. The pump has bad bearing in the shaft

Repairs Needed:

Labor and materials to replace leaking pump.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (See attached detail, includes tax and shipping)	--	--	\$2,423.56	--	\$2,423.56
--	NA	TW Labor (repair and diagnostic)	13	80	--	--	\$1,040.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
13	\$1,040.00	\$2,423.56	\$0.00	\$3,463.56	100%	\$3,463.56



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	VA011
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Bill Davis/ Richard Walker		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace leaking pump.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Armstrong Pump 116475-132	1	\$2,181.96		\$2,181.96
Freight	1	\$125.00		\$125.00
Sales Tax				\$116.60
Diagnostic Labor			5	\$400.00
SUB-TOTAL COSTS:		Materials Total	\$2,423.56	Labor \$1,040.00
		TOTAL		\$3,463.56

Order #	71370139-00
Terms	1% 10th prox, Net 30 prox
Customer P/O	QUOTE

Bill To: 1127319
TIDEWATER INC 447
6625 SELNICK DRIVE
ELKRIDGE, MD 21075

Ship To
TIDEWATER INC 447
6625 SELNICK DRIVE
ELKRIDGE, MD 21075

Branch:
United Refrigeration Inc.
960 West 12th Street
Erie, PA 16501
(814)454-6900 FAX#: (814)454-9104
branchX3@uri.com

Cust#: 1127319	Order Date: 12/02/19	Whse: 0X3	Taken By: MA	Sales out: 447A
----------------	----------------------	-----------	--------------	-----------------

Special Instructions: **QUOTED BILL** Ref:

Product Ln# And Description	Quantity Ordered	Quantity B.O.	Quantity Shipped	Qty. UM	Unit Price	Amount (Net)
PUMP IS IN STOCK AT SUPPLIER. 2-3 DAY LEAD TIME.						
1 116475-132	1			each	1818.30	1818.30
ARMSTONG CIRCULATOR PUMP						
1 Lines Total					Total	1818.30
					Freight In	125.00
					Taxes	116.60
					Invoice Total	2059.90
** NOT AN INVOICE OR RECEIPT **						

** This Quote Will Expire On: 01/01/20 **

I acknowledge that this order includes non-stock merchandise ordered by United Refrigeration specifically on my behalf. I further agree that the product meets the proper specification requirements and that I will accept delivery of the product upon receipt by United Refrigeration and make payment within the standard agreed upon terms.

ALL NON-STOCK ORDERS ARE SUBJECT TO ACTUAL INBOUND FREIGHT CHARGES INCURRED!

Signature:

Printed Name:

Date:

