

Additional Funding Request

DE007	CSS# 22801 WO# 11434 Asset# Boilers assets 1731, asset 1732							
Description of Repairs	Labor and materials needed to install a new union in the relief discharging piping to access and inspect the inlet of the boiler and be able to remove discharge like for other applications. Complete a system check to ensure everything is running properly.							
Diagnosis: Initial Work Order	Boiler #1 & #2 - Need union installed between boiler and safety valve							
Diagnostic Fee	\$500							
Additional Labor Cost to Perform Repairs	<p>\$ 900</p> <p>Labor \$100/hr x 9</p>							
Additional Cost	<p>\$ 83.73</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Union Fitting/Pipe/Coupling See detail in Quote</td> <td style="width: 10%;">1</td> <td style="width: 10%;">\$83.73</td> <td style="width: 10%;">\$83.73</td> </tr> </table>				Union Fitting/Pipe/Coupling See detail in Quote	1	\$83.73	\$83.73
Union Fitting/Pipe/Coupling See detail in Quote	1	\$83.73	\$83.73					
Total Cost of Repair	\$ 1,483.73							



S&S MECHANICAL

S&S Mechanical
4845 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 157

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 11434
Quote No: 157
Site: DE007 Olgetown Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 01/14/2020
Valid For: 30 Day(s)

WO#: 11434

CSS Ticket Number: 22801

Problem: Boiler #1 & #2 need union should be on the discharge side of the valve.

S&S proposes to finish and install the following:

S&S will install a new union in the relief discharge piping to be able to access and inspect the inlet of the boiler and be able to remove discharge like for other applications.

S&S will then complete a system check to ensure everything is working properly.

Service

Item	Quantity	Unit Price	Total
1" Copper Pipe	1.00	\$42.00	\$42.00
1" Copper Union Fitting	2.00	\$15.31	\$30.62
1" Copper Coupling	2.00	\$3.56	\$7.12
Tax	1.00	\$3.99	\$3.99
Diagnosis Fee	1	\$500.00	\$500.00
Plumbing Labor Rate	9	\$100.00	\$900.00
Sub-Total ex Tax			\$1,483.73
Tax			\$0.00
Total inc Tax			\$1,483.73

Labor	\$1,400.00
Materials	\$83.73
Sub-Total ex Tax	\$1,483.73
Tax	\$0.00
Total inc Tax	\$1,483.73

Shopping Cart



FREE Shipping on eligible items. See Details

Item	How To Get It	Qty	Item Total
 Everbilt 1 in. Copper Pressure... Model #C600HDI	<div> In-Store Pick Up FREE</div> <div> Ship to Home Order within 4 hrs 32 mins get it by Thu, Jan 16 FREE</div> <div> Express Delivery Starting at \$8.99 for delivery</div>	<input type="text" value="2"/>	\$5.94 \$2.97/Item
			Save for Later Save to Favorites Remove
 Everbilt 1 in. Copper Pressure... Model #C633WHD1	<div> In-Store Pick Up FREE</div> <div> Ship to Home Estimated Arrival: Tue, Jan 21 FREE</div> <div> Express Delivery Starting at \$8.99 for delivery</div>	<input type="text" value="2"/>	\$25.52 \$12.76/Item
			Save for Later Save to Favorites Remove
Get Bulk Pricing of \$28.00 on this item when you purchase at least 10 units.			
 Cerro 1 in. x 10 ft. Copper Type L... Model #1 L 10	<div> In-Store Pick Up 10 in stock at Oxon Hill, MD 20745 Change FREE</div> <div> Ship to Home</div> <div> Express Delivery Starting at \$8.99 for delivery</div>	<input type="text" value="1"/>	\$35.00 \$35.00/Item
			Save for Later Save to Favorites Remove

PULSE
combustion



Fulton



FHW

PULSE
combustion



Fulton

