

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VAD06 Date of Visit: 12.27.19

Contractor Personnel on Site:

- |                          |          |
|--------------------------|----------|
| 1. <u>Richard Walker</u> | 4. _____ |
| 2. _____                 | 5. _____ |
| 3. _____                 | 6. _____ |

**Service Call Number**

CSS# 23200 WO# 11567

**Description of Repairs**


Found Boiler #2 cut out on low water.  
Added water. Boiler #2 working.  
Boiler #1 (Needs inducer motor Assembly).

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Richard Walker Date: 12.27.19

Signed: 


To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Donald L Huson Date: 12.27.19

Signed: 

E-Mail: \_\_\_\_\_



Boiler #2 VA006 -  
Lockout, Lockout cleared.