

## **CERTIFICATION OF WORK SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD002 B-7 Date of Visit: 10/02/20

#### Contractor Personnel on Site:

1. John Brown
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

## Service Call Number

CSS# 24065 WO# 11944

## Description of Repairs

repair sheetrock and regular cove base and installed 3 sheets of plywood as bumper guards and painted them, In vault area.

## **CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Johnny W Brown Date: 10/02/20

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SFC Cesar Torres Date: 10/02/20  
Signed: Cesar Torres

E-Mail: \_\_\_\_\_

