

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA049 Date of Visit: 3/18/2020

Contractor Personnel on Site:

- | | |
|---------------------------|----------|
| 1. <u>CHARLES GRESHAM</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 24219 WO# 11953

Description of Repairs


Reset tripped breaker restoring power to receptacles in offices 1012 and 1015.

Breaker held after computers/monitors had been plugged in.

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Charles Gresham Date: 3/18/2020

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Ken Ross / SFC Date: 18 March 2020

Signed: 

E-Mail: Kenneth.d. Ross.mil@mail.mil



120.9
Volts
AC



V

V

Ω

A

+

OFF

FLUKE 373 TRUE RMS CLAMP METER

CAUTION
CAT II 300V



CAT III 600V
CAT IV 300V

600A

FLUKE 373 TRUE RMS CLAMP METER

⎓

~A

Ω

V

~V

OFF

☀

Volts

AC

⚡

120.7

CAT III 600V
CAT IV 300V

COM

⏏

VΩ