

Additional Funding Request

MD024	CSS# 25535 WO# 13823 Asset# NA							
Description of Repairs	Labor and material to replace hinge and drill new holes in mens bathroom stall.							
Diagnosis: Initial Work Order	Bldg. 1003 - Men's bathroom handicap stall door closer is not working - leaving the door hanging open (out) when the stall is not in use.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 240</p> <p>Labor \$80/hr x 3</p>							
Additional Material Cost to Perform Repairs	<p>\$ 39.98</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Parts</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">39.98</td> <td style="width: 10%; text-align: center;">39.98</td> </tr> </table>				Parts	1	39.98	39.98
Parts	1	39.98	39.98					
Total Cost of Repair	\$ 439.98							



WORK ESTIMATE

CSS #:

25535

Work Order #:

13823

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	MD024
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	John Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and material to replace hinge and drill new holes in mens bathroom stall.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
D&D 2-7/8 in. x 3-3/4 in. Black Self-Closing Metal Gate Hinge	1	\$39.98		\$39.98
Labor			3	\$240.00
SUB-TOTAL COSTS:	Materials Total	\$39.98	Labor	\$400.00
		TOTAL		\$439.98

Pasadena, MD



Search



in. Black Self-Closing Metal Gate

★★★★★ (54)

\$31.73



Find it at Pasadena, MD #2582



4 in stock

Aisle: 09 Bay: 006



Check Nearby Stores

\$31.73



Save up to \$100 on your qualifying purchase.



Home



Shop



Johnny



Stores

...

More

