

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA048 Date of Visit: 12.23.2020

Contractor Personnel on Site:

1. <u>Richard Walker</u>	4. _____
2. _____	5. _____
3. _____	6. _____

Service Call Number

CSS# 27033 WO# 12916

Description of Repairs

confirmed locations of real placement.

drilled 1/2in holes, utilized REDEYE concrete anchors.

hung reels, tightened reels to wall.

note wall between bay doors started breaking on bottom right anchor., bottom left of other reel. so real has 3 anchors.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Richard Walker Date: 12.23.2020

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:


Print Name/Rank: WARRREN GATHER Date: 12.23.2020

Signed: 

E-Mail: _____



bottom right hole in concrete started to crumble, reel has 3 anchors.



bottom left hole started breaking surrounding concrete with anchor, tried cutting bolt out, will return with slip anchor for individual hole. reel has 3 anchors

