

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VIA011 Date of Visit: 12-8-20

Contractor Personnel on Site:

1. Moers
2. Paul Markham
3. _____
4. _____
5. _____
6. _____

Service Call Number

CSS# 27506 WO# Com0142369

Description of Repairs

pulled .7 pounds of R22 out of system. pumped with nitrogen. Found leak in valve core. Replaced valve core and pulled vac to 230 mic and charged with 2.3 pounds R22. Started system up. 1st unit run will rerun in morning to check on unit.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Paul Markham Date: 12-8-20
Signed: Paul

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Chris Chipp Date: 12/8/20
Signed: CC

E-Mail: _____