

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039 BLDG1 Date of Visit: 1/5/21 , 1/8/21

Contractor Personnel on Site:

1. <u>Patrick Brown</u>	4. <u>Hyde-Stone</u>
2. _____	5. _____
3. _____	6. _____

**Service Call Number**

css# 27632 wo# 10712

**Description of Repairs**

The old nonfunctioning flame assemblies on both boilers were removed and new flame assemblies were installed repiped rewired and tested for proper operation

---

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Patrick Brown Date: 1/8/21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SSGT HECTOR SOTO Date: 1/8/21

Signed: 

E-Mail: \_\_\_\_\_

