

Additional Funding Request

| | | | | | | | | |
|---|---|--------|--------|--|---|---|--------|--------|
| MD003 | CSS# 28224 WO# 13449 Asset# NA | | | | | | | |
| Description of Repairs | S&S proposes to remove and replace the sequencer module. S&S will then complete a system check to ensure the system is running as intended. | | | | | | | |
| Diagnosis: Initial Work Order | The boiler in the OMS building is not completing its start up cycle and will not stay running. This is the main source of heat in the building. There are a couple of old box heaters throughout that will help keep the lines from freezing but as the days get colder, this will become more difficult for them to do. | | | | | | | |
| Diagnostic Fee | <p>\$ 450</p> <p>S&S Labor \$100/hr x 4.5</p> | | | | | | | |
| Additional Labor Cost to Perform Repairs | <p>\$ 900</p> <p>S&S Labor \$100/hr x 9</p> | | | | | | | |
| Additional Material Cost to Perform Repairs | <p>\$ 567.28</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">SAFe40 V4/S07840/244365 (plus shipping)</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">567.28</td> <td style="padding: 2px; text-align: right;">567.28</td> </tr> </table> | | | | SAFe40 V4/S07840/244365 (plus shipping) | 1 | 567.28 | 567.28 |
| SAFe40 V4/S07840/244365 (plus shipping) | 1 | 567.28 | 567.28 | | | | | |
| Total Cost of Repair | \$ 1917.28 | | | | | | | |



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 479

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 13449
Quote No: 479
Site: MD003 Liberty Heights
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 01/14/2021
Valid For: 30 Day(s)

WO#: 13449

CSS Ticket Number: 28224

SOW: The boiler in the OMS building is not completing its start up cycle and will not stay running.

S&S was onsite and troubleshooted the boiler had a bad sequencer module.

S&S proposes to remove and replace the sequencer module.

S&S will then complete a system check to ensure the system is running as intended.

Service

| Item | Quantity | Unit Price | Total |
|-------------------------|----------|-------------------------|------------|
| SAFe40 V4/S07840/244365 | 1.00 | \$517.28 | \$517.28 |
| Shipping | 1.00 | \$50.00 | \$50.00 |
| Diagnosis Fee | 1 | \$450.00 | \$450.00 |
| HVAC Labor Rate | 9 | \$100.00 | \$900.00 |
| | | Sub-Total ex Tax | \$1,917.28 |
| | | Tax | \$0.00 |
| | | Total inc Tax | \$1,917.28 |

| | |
|-------------------------|------------|
| Labor | \$1,350.00 |
| Materials | \$567.28 |
| Sub-Total ex Tax | \$1,917.28 |
| Tax | \$0.00 |
| Total inc Tax | \$1,917.28 |



JOHNSTONE ANNAPOLIS
1981 MORELAND PKWY, SUITE 101
ANNAPOLIS, MD 21401
410-280-0101
Fax 410-280-0104

Quotation

| EXPIRATION DATE | QUOTE NUMBER |
|--|--------------------|
| 03/15/2021 | 100-100943897 |
| JOHNSTONE ANNAPOLIS 1981 MORELAND PKWY, SUITE 101 ANNAPOLIS, MD 21401 410-280-0101 Fax 410-280-0104 | PAGE NO. 1 of 1 |

QUOTE TO:

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

SHIP TO:

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

| CUSTOMER NUMBER | CUSTOMER PO NUMBER | JOB NAME / RELEASE NUMBER | SALESPERSON | |
|-------------------------------------|---|---------------------------|-------------|-----------------|
| 14831 | MD003 WO# 13449 | HOUSE | | |
| WRITER | SHIP VIA | TERMS | SHIP DATE | FREIGHT ALLOWED |
| Jimmy Schropp - Anna 43 | PICK UP | Net 10th Prox | 01/14/2021 | No |
| ORDER QTY | DESCRIPTION | UNIT PRICE | EXT PRICE | |
| 1ea | 8738803949 SAFe40 V4/S07840 US * Non Returnable / Non refundable Pn: 244365 | 431.067/ea | 431.07 | |
| Quotation Valid For 20 Days. | | Subtotal | 431.07 | |
| | | S&H Charges | 25.00 | |
| | | Estimated Tax | 25.86 | |
| | | Amount Due | 481.93 | |



Certified by
Bosch Thermotechnik GmbH

MAWP, water 50 psi
Maximum water temp 200 °F
Minimum relief valve capacity 451 lb/h

Ser.-no. 2530-010-300007-7747014548

Version: 03



| Mod | GB312 120 | Category | IV |
|-----|-----------|----------|----|
|-----|-----------|----------|----|

| | |
|----------------------|------------|
| Input rating max | 441 MBtu/h |
| Output rating | 409 MBtu/h |
| Input rating min | 132 MBtu/h |
| Orifice size nat-gas | 17.0mm |

| | | |
|---------------------|-------------|------------------|
| Gas supply Pressure | 3.5 - 10.5 | |
| Electrical Rating | 120 V | Fuse 5.0 A 60 Hz |
| Fuel | Natural gas | |

Hot Water Boiler low pressure.

This appliance requires a special venting system.

Refer to installation instructions for parts list and method of installation.

For either direct vent installation or for installation using indoor combustion air.

ANSI
CAN/CSA
CRN

ANS Z21.13b-2007
CSA 4.9b-2007
7834.7C



Bosch Thermotechnik GmbH

D-59873 Wetzlar GERMANY