

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA050 Date of Visit: 2/22/2021

Contractor Personnel on Site:

1. <u>Tate Hall</u>	4. _____
2. _____	5. _____
3. _____	6. _____

Service Call Number

CSS# 29130 WO# 29130

### Description of Repairs

Found building heat not working due to tripped motor starts for boiler circulation pumps. Boiler heating but water not circulating. Reset motor starts and tested operation and amp draw. Verified zones began heating in EMS software.

Equipment is now heating.

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Tate Hall Date: 2/22/2021

Signed: T Hall

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: GRENIER,SCOTT,ANTHONY NY.1007219551

Digital signed by  
GRENIER,SCOTT,ANTHONY,1007219551  
Date:2021/02/25 14:36:29 -05:00

E-Mail: \_\_\_\_\_

File Edit Format View Help

Emergency Exit Locations

EMERGENCY EXIT LOCATIONS

Previous

AR01 1

AR01 2

AR02 1

AR02 2

EMR 1

EMR 2

EMR 3


EMR 4

AFRC

Monday, 27/05/2013 14:30 CDT

First Floor

Second Floor



THIRD FLOOR

