

CERTIFICATION OF WORK
SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA049 Date of Visit: 3-8-2021

Contractor Personnel on Site:

- | | |
|---|----------|
| 1. <u>Bobby Barton/ Double-B Handyman</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 29366 WO# 13864


Description of Repairs

Removed screws wood glue wood to fill the
void. Let it dry and Reinstalled the same
screws.

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Robert S. Barton S.A. Date: 3-8-2021

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: ANDERSON, MARK GS-12 Date: 8 MAR 21

Signed: 

E-Mail: mark.s.anderson7.mil@mail.mil





ATTENTION
Let us be mindful of one another & clean up behind ourselves.
Place all weights back.
Let's keep our exercise area clean & neat.
Thank you!

Men's Restroom

Let us be mindful of one another & clean up behind ourselves.
Place all weights back.
Let's keep our exercise area clean & neat.
Thank you!