CERTIFICATION OF WORK
SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD-24 Date of Visit: 4/8/2021

Contractor Personnel on Site:

1. Jeremy Sneathen 4. _____
2. _____ 5. _____
3. _____ 6. _____

Service Call Number

CSS# 29464 WO# 13886
CSS# 26450 WO#. 13977

Description of Repairs

Clean main air handler in building 1003
Repair duct insulation in building 1003

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jeremy Sneathen Date: 4/8/2021

Signed: _____

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: PETE STRAB Date: 8 APR 21

Signed: _____

E-Mail: _____

Model Number MC60D3XH1B
Serial Number (S) SA0F8967012

CAUTION / ATTENTION

Do not use full-strength coil cleaner on coil. Refer to instructions. Full-strength coil cleaner will damage fin coating and pre-painted surfaces.

N'utilisez pas un nettoyeur de serpentin pur sur le serpentin. Référez-vous aux instructions. Un nettoyeur pur endommagera la surface des ailettes ainsi que les surfaces peinturées.

CAUTION / ATTENTION

Do not use full-strength coil cleaner on coil. Refer to instructions. Full-strength coil cleaner will damage fin coating and pre-painted surfaces.

N'utilisez pas un nettoyeur de serpentin pur sur le serpentin. Référez-vous aux instructions. Un nettoyeur pur endommagera la surface des ailettes ainsi que les surfaces peinturées.

Serial Number (S) SA0A8575185

SA0A8575185

ASTM D 2855 SCH 40 · 280 PSI PR WATER AT 73°F

2" CRE FLINE® PVC DWV