

## Additional Funding Request

### INVOICE

<b>MD002</b>	<b>CSS# 29533 WO# 13893 Asset# NA</b>			
Description of Repairs	Secured power to the broken floor receptacle by turning off the breaker.			
Diagnosis: Initial Work Order	There is an open electric line on the floor of the kitchen that is sparking during the kitchen cleaning .All the soldiers were removed from the kitchen and were advised not to go back into kitchen area			
Diagnostic Fee	\$ 0			
Additional Labor Cost to Perform Repairs	\$ 640 TWI Emergency Labor \$160/hr x 3 TWI Emergency Coordination \$160/hr x 1			
Additional Cost	\$ 0			
	N/A	1		
Total Cost of Repair	\$ 640			

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD002 B-1 Date of Visit: 03/14/21

Contractor Personnel on Site:

1. <u>John Brown</u>	4. _____
2. _____	5. _____
3. _____	6. _____

**Service Call Number**

CSS# 29533 WO# 13893

**Description of Repairs**

I secure the power to the broken floor receptacle  
\_\_\_\_\_  
\_\_\_\_\_

**CERTIFICATION OF WORK**

To be signed by the Contractor:


Print Name: Johnny W Brown Date: 03/14/21

Signed: \_\_\_\_\_

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Capt. Marlin Lynch Date: 03/14/21

Signed: 

E-Mail: \_\_\_\_\_