

**Additional Funding Request  
INVOICE**

<b>MD024</b>	<b>CSS# 29802 WO# 13967 Asset# NA</b>							
Description of Repairs	B&P Environmental came out and pumped out 2000 gallons out of septic tank. John Brown checked out the power and pump operation. S&S came out and snaked the ladies room because the drains were still slow. Everything running properly.							
Diagnosis: Initial Work Order	Received a text from Mark Smith stating that the bathroom floor drains have sewage coming up from them. Mr. Smith stated that it is only the drain/s in the ladies restroom. Spoke with Mr. Augustin and he stated that there is a history of the tenants flushing wipes down the drains, may need to have the lines snaked.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 1985</p> <p>SS- \$100/hr x 6</p> <p>B&amp;P- Pump 2000 gallons/ \$745</p> <p>TWI- \$80/hr x 8</p>							
Additional Cost	<p>\$ 45</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">K60 (S&amp;S)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 15%; text-align: right;">45.00</td> <td style="width: 15%; text-align: right;">45.00</td> </tr> </table>				K60 (S&S)	1	45.00	45.00
K60 (S&S)	1	45.00	45.00					
Total Cost of Repair	\$ 2030							

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD024 B-1 Date of Visit: 03/30,31/21

Contractor Personnel on Site:

1. <u>John Brown</u>	4. _____
2. <u>B&amp;P Environmental</u>	5. _____
3. <u>S&amp;S</u>	6. _____

**Service Call Number**

CSS# 29802 WO# 13967

### **Description of Repairs**

---

B&P ENVIRONMENTAL came out and pumped out 2000 gallons out of Septic tank . I checked out the power and the pump operation. S&S came out and snake the Ladies room because the drains were still slow. everything works fine now.

---

## CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Johnny W Brown Date: 03/31/21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank CW5 Mark Smith Date: 03/31/21

Signed: 

E-Mail: \_\_\_\_\_



**S&S Mechanical**  
4831 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
www.sandsmidatlantic.com

PLEASE PAY BY	AMOUNT	INVOICE DATE
<b>04/30/2021</b>	<b>\$645.00</b>	<b>03/31/2021</b>

Tidewater, Inc.  
Tidewater, Inc  
6625 Selnick Dr.  
Suite A  
Elkridge MD 21075

## INVOICE NO. 82400

**Job Name:** 13967  
**Site:** MD024 Ordnance Road  
**Site Address:** 720 Ordnance Road  
Baltimore MD 21226

### Description

**WO#:** 13967

**CSS Ticket Number:** 29802

**Problem:** B&P is currently onsite w/John Brown pumping out 2,000 gallons-This is complicated there are (4) holding tanks and the last tanks in line -it's possible the pumps are not working to pump the gray water to the drain fields . Tomorrow at 8am -S&S with John Brown will be onsite to Snake from the ladies bath room to unstop the building blockage and investigate the pumps not working The bathroom floor drains have sewage coming up from them. Mr. Smith stated that it is only the drain/s in the ladies restroom. Spoke with Mr. Augustin and he stated that there is a history of the tenants flushing wipes down the drains, may need to have the lines snaked.

### Josh Stephenson 03/30/2021 Work Note

After locating back up, checked septic tank and it is full and will need to be pumped out. Informed Mary of our findings and she scheduled B&P to come and pump out.

### Josh Stephenson 03/31/2021 Work Note

Meet John Brown onsite and snaked women's bathroom drains. Ran all sinks to make sure drains are clear and working when finished. Work complete.

### 8491 - Service

Item	Quantity	Unit Price	Total
K60	1.00	\$45.00	\$45.00
Plumbing Labor Rate	6.00 hrs	\$100.00	\$600.00
		<b>Labor</b>	\$600.00
		<b>Materials</b>	\$45.00
		<b>Sub-Total ex Tax</b>	\$645.00

Make all checks payable to S&S Mechanical. Overdue accounts are subject to a service charge of 1.5% per month. Thank you for your business.

**-S&S Mechanical also accepts all major credit cards. Call 301-574-1555 to pay an invoice via credit card-**

<b>Sub-Total ex Tax</b>	\$645.00
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$645.00
<b>Amount Applied</b>	\$0.00
<b>Balance Due</b>	\$645.00

# Invoice

## B&P Environmental One LLC

1230 Cronson Blvd.

Crofton, MD 21114

410-721-7091



Date	Invoice #
3/30/2021	T5208

Bill To

Tidewater Inc.  
6625 Selnick Drive  
Suite A  
Elkridge, MD 21075

Terms	Project
Due on receipt	720 E Ordinance Rd

Quantity	Description	Rate	Amount
1	B&P received call 3/30/2021 for emergency pumping of septic tank. Mark Smith 410-353-1800 Contact on site. John Brown 443-346-4349 Tech on site. CSS# 29802 3/30/21, 2000 gallons pumped.	745.00	745.00
<b>Total</b>			\$745.00



# B&P Environmental One LLC Work Ticket

\*\*\*

Bill To  
Tidewater Inc.  
6625 Selnick Drive  
Elkridge, MD 21075

Service Address  
720 E Ordinance Rd  
6625 Selnick Drive  
Baltimore, MD 21226

Due Date	3/30/2021
Order #	T5208
PO #	
Balance	\$0.00

Phone 410-967-5346

Alt Contact

Alt Phone

Email mary.lowery@tideh2o.net

Contact

Description of Work:

B&P received call 3/30/2021 for emergency pumping of septic tank. Mark Smith 410-353-1800 Contact on site. John Brown 443-346-4349 Tech on site.

Work Performed  
Pumped down septic tank and cleaned  
out the solids  
pumped out 3000 gal

Date	Employee	Labor	Time In	Time Out	Total	Qty	Material	Description	Cost
3/30/21	BRENT	130		340					

CSS 29802

WO 13967

MD 024

Date:

3/30/21

Customer Authorization/Signature:

X J.W. Brown Johnny W. Brown

Completed By:

Brent

1230 Cronson Blvd  
Crofton, MD 21114  
www.BandPEnvironmental.com  
410 721 7091







