

CERTIFICATION OF WORK
SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: va049 Date of Visit: 10-6-21

Contractor Personnel on Site:

- | | |
|-----------------------|----------|
| 1. <u>Chadd Cox</u> | 4. _____ |
| 2. <u>Dean Runyon</u> | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 30363 WO# 14155


Description of Repairs

Rewire power for AHU-5 and Reconnect power
Supply to Fan Coil #7. FCU#7 motor is bad & needs to be
replaced. The water valve actuator needs to be ~~re~~ re installed.
AHU-5 needs to have fan motor replaced because it appears
the shaft or pulley is bent. Squirrel Cage spins but is really restricted.

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Chadd Cox Date: 10-6-21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: GS12 MARK ANDERSON Date: 6 Oct 21

Signed: 

E-Mail: mark.s.anderson7.civ@army.mil



FCU-7
AFTER

Kitchen
Panel
CKT #19

FCU-7
BEFORE





