



# S&S MECHANICAL

**S&S Mechanical**  
4831 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
www.sandsmidatlantic.com

PLEASE PAY BY

**04/24/2022**

AMOUNT

**\$640.00**

INVOICE DATE

**03/25/2022**

Tidewater, Inc.  
Tidewater, Inc  
6625 Selnick Dr.  
Suite A  
Elkridge MD 21075

**INVOICE NO. 88572**

**Job Name:** 16888  
**Site:** DE001 North New Street  
**Site Address:** 344 North New Street  
Dover DE 19904

## Description

**WO#: 16888**

**CSS Ticket Number: 30500**

**Problem:** There is damaged barbed wire and loose mounts along the fence line.

## Joe Moore 03/24/2022 Work Note

Walked fence line, checked for loose outriggers, secured as needed.

Tightened and secured barbed wire as needed. Work complete.

## 10774 - Service

Item	Quantity	Unit Price	Total
General Maintenance Labor Rate	8.00 hrs	\$80.00	\$640.00
<b>Labor</b>			<b>\$640.00</b>
<b>Sub-Total ex Tax</b>			<b>\$640.00</b>

Make all checks payable to S&S Mechanical. Overdue accounts are subject to a service charge of 1.5% per month. Thank you for your business.

<b>Sub-Total ex Tax</b>	\$640.00
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$640.00
<b>Amount Applied</b>	\$0.00
<b>Balance Due</b>	\$640.00

**-S&S Mechanical also accepts all major credit cards. Call 301-574-1555 to pay an invoice via credit card-**

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE 001Date of Visit: 3/24/22

Contractor Personnel on Site:

1. Joe Moore

4. \_\_\_\_\_

2. \_\_\_\_\_

5. \_\_\_\_\_

3. \_\_\_\_\_

6. \_\_\_\_\_

## Service Calls – Service Call Number and Description

1. fence repair

2. \_\_\_\_\_

3. \_\_\_\_\_

WO # 16888CSS # 30500

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Joseph MooreDate: 3/24/22Signed: Joseph Moore

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SGT Jayobbe Lopez Date: 3/24/22Signed: [Signature]

E-Mail: \_\_\_\_\_























