

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE 007

Date of Visit: 8/26/2021

Contractor Personnel on Site:

1. B. Davis

2. _____

3. _____

4. _____

5. _____

6. _____

Service Calls – Service Call Number and Description

1. Chilled water pipe leaking and sweating

2. _____

3. _____

WO # 14538

CS # 31496

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: BRIAN DAVIS

Date: 8/24/2021


Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: JASON GAVIN AFOS

Date: 8/26/21

Signed: 

E-Mail: _____

HEATING HOT WATER RETURN →

CHILLED WATER RET. →

CHILLED WATER SUP. ←

LED WATER SUP. →





180L

LITERS

140L

100L

60L

20L

RPI
54

INBCO
100% POLYETHYLENE
GLASS REINFORCED

Solenoid Valve
Low Voltage 12V DC
1/2" NPT x 1/2" NPT x 1/2" NPT
1/2" NPT x 1/2" NPT x 1/2" NPT
1/2" NPT x 1/2" NPT x 1/2" NPT
1/2" NPT x 1/2" NPT x 1/2" NPT

CAUTION
1. BE SURE TO USE A BACKUP
WRENCH WHEN CONNECTING
2. DO NOT OVERTIGHTEN
3. WORKING OVER THE TANK
4. WEAR PROTECTIVE GEAR

Yellow tag with handwritten text

HEATING HOT WATER RETURN →

CHILLED WATER RET. →

CHILLED WATER SUP. ←

LED WATER SUP. →





180L

LITERS

140L

100L

60L

RPIC
54
120v

DE-007