

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Brandt Date of Visit: 12-13-21

Contractor Personnel on Site:

- | | |
|-------------------------|----------|
| 1. <u>Keith Pearson</u> | 4. _____ |
| 2. <u>Austin Carman</u> | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 32964 WO# 15353 EST# 1870


Description of Repairs

Re-set All CPUs to regain Communications to All Buildings
Performed A complete System test. Found the following.
Bld-314 - Needs New Power Supply, New DSI Board, New Strike
5- 12V-12AH BATTERIES.
Found defective Reader @ main ENT to Bld 2. Replaced Reader ★

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Keith Pearson Date: 12-13-21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: _____

E-Mail: _____

Loop/Cluster:

GTA Brandt USARC

Command:

Get Controller In

Controller Name

Nu...

CPU #

Model...

Serial Nu...

- | | Controller Name | Nu... | CPU # | Model... | Serial Nu... |
|-------------------------------------|---|-------|-------|----------|--------------|
| ☒ |  Building 001 IT RM 1... | | | | |
| ☒ |  Bulding 004 OMS (C... | | | | |
| ☒ |  Bldg 314 (CPU # 1) | | | | |
| ☒ |  Building 002 IT RM ... | | | | |

Alarm Events

GTA Brandt USARC

Alarm

Loop/Cluster:

GTA Brandt USARC


Controller Name


Nu...

CPU #

Mode

☒		Building 001 IT RM 1...	001	1	635
☒		Bulding 004 OMS (C...	002	1	635
☒		Bldg 314 (CPU # 1)	003	1	635
☒		Building 002 IT RM ...	004	1	635





LE120703

