

CSS Ticket Number: 33002

Service Call Priority (emergency, urgent, routine): Routine

Name, Office and Command of Requestor: Jason Gavin, AFOS

Type of Funding (COR Input)

Paying Activity Code (PAC) (COR Input)

Date and time call received

Specific craft designation(s): Handyman

Callers' description of the problem or requirement:

The armature gate leading into the OMS and MEP area has broken. From looking at the pictures provided by SFC Williams, it looks like the damage may be due to rot and weathering. I would recommend to replace the arm with an arm made of something to withstand the elements better.

POC is SFC David Williams at 817-846-4096 or david.c.williams2.mil@mail.mil or Mr. Cloaninger at 910-598-8408 or michael.b.cloaninger.civ@mail.mil.

Associated Asset ID number: MD066

Description of equipment or system (type of equipment, size, serial number): Unknown







