

Region: 5

Location: VA099

CSS #: 33360

Maximo Work Order No.: 15412

Asset #: NA

Date Issued: 11/9/21

Original Description: Propane gas light on commercial gas stove is out.

Repairs Needed:

S&S proposes to check all kitchen equipment, replace any piping or fittings that may have leaked and ensure the pilot light on the stove is working properly. S&S will then put all boilers back online and get the material and info needed to submit a quote to install CO detectors & LP gas detectors as required by safety.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	SS Labor (3 men)	48	\$100.00	--	--	\$4,800.00
--	NA	TW Coordination	4	\$80.00	--	--	\$320.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
52	\$5,120.00			\$5,120.00	100%	\$5,120.00



S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 806

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 15412
Quote No: 806
Site: VA099
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 11/09/2021
Valid For: 30 Day(s)

WO#: 15412

CSS Ticket Number: 33360

Problem: Propane gas pilot light on commercial gas stove is out.

S&S hereby proposes to check all kitchen equipment, replace any piping or fittings that may have leaked and ensure the pilot light on the stove is working properly. S&S will then put all boilers back online and get the material and info needed to submit a quote to install CO detectors & LP gas detectors as required by safety.

Service

Item	Quantity	Unit Price	Total
Labor	1	\$4,800.00	\$4,800.00
		Sub-Total ex Tax	\$4,800.00
		Tax	\$0.00
		Total inc Tax	\$4,800.00

Labor	\$4,800.00
Sub-Total ex Tax	\$4,800.00
Tax	\$0.00
Total inc Tax	\$4,800.00