

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA701 Date of Visit: 11-18-21

Contractor Personnel on Site:

- |                      |          |
|----------------------|----------|
| 1. <u>Jacob Long</u> | 4. _____ |
| 2. _____             | 5. _____ |
| 3. _____             | 6. _____ |

**Service Call Number**

CSS# 33428 WO# 15416

**Description of Repairs**

attempted to clean ceiling tiles, will quote to replace  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Jacob Long Date: 11-18-21

Signed: \_\_\_\_\_

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Terry Casey / SFC Date: 18 NOV 2021

Signed: \_\_\_\_\_

E-Mail: terry.l.casey.mil@army.mil







FRAGILE | FRÁGIL | FRAGILE

# 86985.HRC

USG



CGO

**MARS** <sup>TM/MC</sup>  
**HRC**

|                                      |             |
|--------------------------------------|-------------|
| WHITE                                | EDGE   FLB  |
| BLANCO                               | BORDE   FLB |
| BLANC                                | BORD   FLB  |
| 12 PIECES   PIEZAS   PIECES          |             |
| 2 FT. x 2 FT. x 3/4 IN. — 48 SQ. FT. |             |

**Acoustical Panels | Paneles**

ClimaPlus <sup>TM</sup> Warranty

Garantia ClimaPlus <sup>TM</sup>

Garantie ClimaPlus <sup>TM</sup>

All dimensions are nominal. | Todas las dimensiones son nominales. | Toutes les dimensions sont nominales.

**CEILING**

LOOK UP.  
THE CEILING ABOVE YOU  
CONTAINS A MINIMUM OF  
81% RECYCLED CONTENT.