

Additional Funding Request
INVOICE

VA099	CSS# 33851 WO# 15674 Asset# NA			
Description of Repairs	S&S performed analyzer tests throughout building. Had zero parts per million throughout building and only had 14ppm in boiler room at back of boilers. May need to seal metal to PVC connection on boilers to illuminate any possible draft of CO2 in room. No other issues noted. Work complete.			
Diagnosis: Initial Work Order	The boiler alarmed and the odor from the CO2 incident is back at the front door and room 110.			
Diagnostic Fee	\$ 0			
Additional Labor Cost to Perform Repairs	\$ 1,100 SS \$100/hr x 11			
Additional Cost	\$ 0 N/A 1			
Total Cost of Repair	\$ 1,100			

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACTD Building: VAD99 Date of Visit: 12/16/2021

Centre for Personnel on Site

1. Brian Davis	4. _____
2. _____	5. _____
3. _____	6. _____

Service Calls – Service Call Number and Description

1. W0715674 CSS#E98851
2. Forward analysis tests throughout building
3.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Elia Davis Date: 12/14/2021

Signed:  _____

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledge that the contractor was on-site during the identified timeline:

Print Name/Rank: BENJAMIN J. PARRISH, SR GS9/ARA Date: 29OCEMBER2021

Signed: PARRISH,BENJAMIN,JOEL,SR.12542
72830  Digitized and signed by
PARRISH,BENJAMIN,JOEL,SR.1254272830
03/26/2011 11:26:18 AM ET 03/26/2011

E-Mail: BENJAMIN.J.PARRISH.CIV@ARMY.MIL



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

PLEASE PAY BY	AMOUNT	INVOICE DATE
01/16/2022	\$1,100.00	12/17/2021

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

INVOICE NO. 88380

Job Name: 15674
Site: VA099
Site Address: 1117 Harmony Drive
Bedford VA 24523

Description

WO#: 15674

CSS Ticket Number: 33851

Problem: The Boiler alarmed and the odor from the CO2incident is back at the front door and room 110 / The boilers were turned on earlier today and Ben noticed that smell again that they had before when people started getting sick on 05 Nov2021 (when we had to call the fire department). Ben shut the boilers off to be safe.

Brian Davis 12/16/2021 Work Note

Performed analyzer tests throughout building. Had zero parts per million throughout building and only had 14ppm in boiler room at back of boilers. May need to seal metal to PVC connection on boilers to illuminate any possible draft of CO2 in room. No other issues noted. Work complete.

10479 - Service

Item	Quantity	Unit Price	Total
HVAC Labor Rate	11.00 hrs	\$100.00	\$1,100.00
		Labor	\$1,100.00
		Sub-Total ex Tax	\$1,100.00

Make all checks payable to S&S Mechanical. Overdue accounts are subject to a service charge of 1.5% per month. Thank you for your business.

Sub-Total ex Tax	\$1,100.00
Tax	\$0.00
Total inc Tax	\$1,100.00
Amount Applied	\$0.00
Balance Due	\$1,100.00

-S&S Mechanical also accepts all major credit cards. Call 301-574-1555 to pay an invoice via credit card-


NGAS



Combustion Test

Default

O ₂	20.9 %
CO	0 ppm
Eff	— %
CO ₂	— %
T-Stk	65 °F
T-Air	71.7 °F
EA	— %
CO(0)	— ppm
NO	0.0 ppm
NO ₂	0.0 ppm
NOx	0.0 ppm
NO(0)	— ppm
NO ₂ (0)	— ppm
NOx(0)	— ppm
Flow	0.52 LPM



NGAS

Combustion Test

Default

O ₂	20.9 %
CO	2 ppm
Eff	— %
CO ₂	— %
T-Stk	70 °F
T-Air	72.8 °F
EA	— %
CO(0)	— ppm
NO	0.0 ppm
NO ₂	0.0 ppm
NOx	0.0 ppm
NO(0)	— ppm
NO ₂ (0)	— ppm
NOx(0)	— ppm
Flow	0.52 LPM

||    