

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: USARC

Date of Visit: 2-15-22

Contractor Personnel on Site:

1. MOORES Electric

4. _____

2. _____

5. _____

3. _____

6. _____

Service Call Number

CSS# 34096 WO# 15979

Description of Repairs:

Reconfigured Relief valve location to upright
position as per our quote. Redid 1" copper pipe
to connect BACK into existing piping, to drain at
floor. Work was completed on Both Boiler
1+2 onsite.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: MATTHEW Puz Date: 2-15-22

Signed: Matthew Puz

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Diana Ellis, SFC Date: 15 Feb 22

Signed: [Signature]

E-Mail: diana.ellis.mil@army.mil









WEIL-McLAIN
Ultra

Model: Ultra
Series: Ultra
Type: Ultra
Material: Brass
Weight: 10 lbs.
Dimensions: 10" x 10" x 10"

Maximum Water Pressure: 150 psi
Maximum Water Temperature: 200°F
Maximum Gas Pressure: 15" WC
Maximum Gas Temperature: 200°F

WEIL-McLAIN
CERTIFIED BY: [Signature]
Date: [Date]

WEIL-McLAIN
10000
10000