



Proposal

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

April 13, 2022

RE:W/O 16907 CSS#34200 NY001

Sump pump

- Service call
- Remove insulation and inspect piping.

Remove decayed piping and reducing collar.
Replace pipe, collar, and insulation.

1 14" x 60" galvanized pipe(Grainger).	186.12
1 14" - 12" reducing coupling (Grainger)	48.16
1 Insulation repair tape.	28.30

	262.58
8hrs @ 120.00.	960.00

sub-total.	1222.58
20%profit/OH	244.52

Total.	1467.10

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL