

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MP02

Date of Visit: 3/30/22

Contractor Personnel on Site:

1. Josh Stephenson

4. _____

2. Ronald Lustig

5. _____

3. _____

6. _____

Service Calls – Service Call Number and Description

1. 34202 Replace pump Motor.

2. _____

3. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Ronald Lustig

Date: 3/20/22

Signed: [Signature]

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:


Print Name/Rank: Nicholas Chaz SGT

Date: 03/30/22

Signed: [Signature]

E-Mail: _____

BEARING
REPAIR
SEA
11-19-15
P.2










Bell & Gossett®



545747

CUBT 903583

MODEL W V M 48T17D173B

FR 48Z PH 3

AMB 40 INB B3

CODE L ENC DP

DUTY CONT

CAT

K

TYPE T8

DEB

IP 22

HZ 60/50

HP 3/4-1/2

RPM 1725/1425

VOLT 230/460-190/380

FLA 2.8/1.4-2.4/1.2

BF 1.25/1.0


BFA 2.95/1.5

KW 0.5/0.37

PF (COS ϕ) 70.5(0.705)/83.5(0.835)

E-48747

SUITABLE FOR 208V 60HZ 1.0PF



TO REVERSE ROTATION, INTERCHANGE ANY TWO LINE LEADS.

PERMANENTLY LUBRICATED - BALL BEARING

WARNING - FAILURE TO FOLLOW ALL SAFETY INFORMATION CAN RESULT IN SERIOUS PERSONAL INJURY OR DEATH-DISCONNECT ALL POWER BEFORE SERVICING-INSTALL AND GROUND PER LOCAL AND NATIONAL CODES