

## Additional Funding Request

<b>VA701</b>	<b>CSS# 34614 WO# 16753</b>				
Description of Repairs	Labor and materials to change boiler drain filters that are clogged and unclog floor drain that boiler drains into.				
Diagnosis: Initial Work Order	Drain seems to be clogged in room 130 between the 2 boiler controllers.				
Diagnostic Fee	\$ 160  Labor \$80/hr x 2				
Additional Labor Cost to Perform Repairs	\$ 480  Labor \$80/hr x 6				
Additional Material Cost to Perform Repairs	\$ 620  <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Materials (See attached detail)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 15%; text-align: center;">620</td> <td style="width: 15%; text-align: center;">620</td> </tr> </table>	Materials (See attached detail)	1	620	620
Materials (See attached detail)	1	620	620		
Total Cost of Repair	\$ 1260				



# WORK ESTIMATE

CSS #:

34614

Work Order #:

16753

Emergency

Urgent

X

Routine


Company Name:	Tidewater, Inc.		Facility ID:	VA701
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.cology@tideh2o.net">adam.cology@tideh2o.net</a>			
Assigned Technician(s):	Will Schultz			

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT


Labor and materials to change boiler drain filters that are clogged and unclog floor drain that boiler drains into.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Condensate Neutralizer Tube	2	\$254.20		\$508.40
Recharge Kit	2	\$55.80		\$111.60
Labor			6	\$480.00
SUB-TOTAL COSTS:		Materials Total	\$620.00	<u>Labor</u> \$640.00
		TOTAL	\$1,260.00	

TOP VIEW



SIDE VIEW



PART NO.	MBH	GPH	MATERIAL	#PELLETS	INLET PORT	OUTLET PORT
5003	1,500 MAX.	11.0	CLEAR PVC	8.5	1" Sch40	1" Sch40

STANDARD EQUIPMENT:

(2) 1" Acid Proof "Slip in Pipe" Poly Couplings, (4) Stainless Steel Clamps, Clear PVC Tube, MgO Pellets, (2) 1" Split Ring Pipe Clamps with 3/8" threaded rod bases.

**From:** David Wood <[dwood@tla-va.com](mailto:dwood@tla-va.com)>

**Sent:** Thursday, March 10, 2022 10:51:19 AM

**To:** William Schultz <[william.schultz@tideh2o.net](mailto:william.schultz@tideh2o.net)>

**Subject:** [EXTERNAL]JJM Boiler Works Quote Request

**CAUTION: External email, DO NOT click on any links/attachments unless you recognize the sender and know the content is safe**

The JM-6 has been replaced by the following...

Qty-1 CBM-226 (P/N 5003) Condensate Neutralizer Tube \$ 205.00 each

Qty-1 JM06R (P/N 1105) Recharge Kit (pH Power Pellets) \$ 45.00 each

F.O.B. Factory, Plus Freight

Estimated Leadtime to Ship: (3) to (5) Business Days After Receipt of Order