

Additional Funding Request

MD002	CSS# 35157 WO# 16908 Asset# NA							
Description of Repairs	S&S will remove and dispose of the damaged mirror and install a new 60 x 96 mirror with polished edges.							
Diagnosis: Initial Work Order	Repair damaged mirror in fitness center, bldg. 001.							
Diagnostic Fee	\$ 160 S&S \$80/ hr x 2							
Additional Labor Cost to Perform Repairs	\$ 720 S&S \$80/hr x 9							
Additional Cost	\$ 1194 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Materials (See attached detail)</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: center;">1194</td> <td style="padding: 2px; text-align: center;">1194</td> </tr> </table>				Materials (See attached detail)	1	1194	1194
Materials (See attached detail)	1	1194	1194					
Total Cost of Repair	\$ 2074							



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 989

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 16908
Quote No: 989
Site: MD002 Ordnance Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 04/07/2022
Valid For: 30 Day(s)

WO#: 16908

CSS Ticket Number: 35157

Problem: Repair damaged mirror in fitness center, bldg. 001.

S&S will remove and dispose of the damaged mirror and install new 60" x 96" mirror with polished edges.

Service

Item	Quantity	Unit Price	Total
Economy Quote 32537	1.00	\$1,194.00	\$1,194.00
Diagnosis Fee	1	\$160.00	\$160.00
General Maintenance Labor Rate	9	\$80.00	\$720.00
Sub-Total ex Tax		\$2,074.00	
Tax		\$0.00	
Total inc Tax		\$2,074.00	

Labor	\$880.00
Materials	\$1,194.00
Sub-Total ex Tax	\$2,074.00
Tax	\$0.00
Total inc Tax	\$2,074.00



Tel: 301-855-9054 7605 Ginger Lane
410-535-5172 Owings, MD 20736
Fax: 301-812-1706
www.economyglass-calvert.com

Quote: 32537

Date: 03/31/2022

Customer

S & S MECHANICAL
4845 SOUTH CRAIN HWY
UPPER MARLBORO MD 20772

Ph:(301)574-1555

Csr: MGR TS Tech: ... Terms: C.O.D

Job: SITE UNSEEN

<u>Qty</u>	<u>Part / Description</u>	<u>Item Total</u>
1.00	REMOVAL - Customer Wall Mirror	165.00
1	60" X 96" MIRROR 1/4 CLEAR POLISHED EDGES	830.00

Notes: Site Unseen- Does not include Jbar or Safety Backing, if required please advise.

Job Site: 700 E. ORDNANCE RD
BALTIMORE MD 21226

Thank you for your Business!

<u>Tax</u>	<u>Total</u>	<u>Payments</u>	<u>Balance</u>
26.40	1,021.40	0.00	1,021.40

