



Facility Repair Proposal

Region: 4C
Fac ID: WV010
Date: 12/1/22

CSS # 90665
Maximo Work Order No.: 11469

Asset ID: NA

Original Work Request:
Replace Repair booster pump on boiler #3

Description of Repairs Needed:
Labor to a.) replace the booster pump with a like for like pump, Hydronic Circulating Pump: Std, Taco, Flanged, 1/6 HP, 33 ft Max. Head, 6 1/2 in Face to Face

Parts List: Taco Circulating Pump #0013-F3

Equipment List: NA

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$1,415.21


Estimate Name: CSS 90665 - WV010 Replace Pump on Boiler 3

ESTIMATE INFORMATION

Client Name: 99th
Estimate Address:
Type: Unit
Measurement System: US Standard
Notes:

COST DATA

Estimate Summary:						Catalog: Facilities and Commercial Renovation	
						Format: MasterFormat 2018	
						Release: Year 2022 Quarter 4	
						Labor Type: Repair & Remodeling	
						City Cost Index: WEST VIRGINIA / CLARKSBURG (263-264)	



GRUNDFOS

NONSUBMERSIBLE CIRCULATION PUMP

Type UP 26-99 F

P/N: 52722361 P1

PC 0804 TC

115 V
60 Hz
10 uF

1 PH

US

Class F
THERMALLY
PROTECTED

FOR INDOOR USE ONLY

$I_L(A)$	$P_i(W)$
2.15	245

MAX FLUID TEMP. 230 F

