

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 10/02/2023 ARRIVAL TIME 10:00 DEPARTURE TIME 2:00 JOB/TICK NO 191325

DEPARTURE TIME 2:00 JOB/TICK NO 191325

JOB/TCK. NO. 191325

CUSTOMER PO. NO. 90977

JOB NAME/LOCATION *USARC - Abingdon VA001*

SERVICE REQUESTED (48) Investment is labor and material to replace the leaking valve on the HW loop.

Manufacture: _____
Model#: _____
Serial#: _____
Refrigerant Added: Qty lb oz TYPE
Refrigerant Removed: Qty lb oz TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Got on site and checked in with Amy. I had them show me the boiler room, then started checking everything out. I located the bad boiler pump and the breaker for it, and found the leaking valve. I checked the new pump and made sure it would, and it would. I didn't have the valve or the parts for the boiler with me, I called Carmela and Shawn had them. Eli is going to get the parts off him and give them to me tomorrow morning. Checked back in with customer after that and let them know i'd be back tomorrow. Packed up everything after that, did paperwork, and then left.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES NO X EXPLAIN

SIGNATURE _____

Customer Representative