

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV046-01 Date of Visit: Dec 14, 2022

Contractor Personnel on Site:

- |                        |          |
|------------------------|----------|
| 1. <u>Ricky Barker</u> | 4. _____ |
| 2. _____               | 5. _____ |
| 3. _____               | 6. _____ |

**Service Call Number**

CSS# 91203 WO# 11547


**Description of Repairs** Upon arrival found neither boiler running. First started by going through casto controls and found multiple alarms, reset alarms and still no boiler operation. Removed top panel on boiler #1 and found ignition control failed in alarm. Reset controller and boiler returned to service. Watched boiler cycle to operating temp several times and made sure all heaters that had been turned off were turned back on.

-----

**CERTIFICATION OF WORK**

To be signed by the Contractor:


Print Name: Richard A. Barker Date: Dec 14, 2022

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Michael Dye/ GS9 Date: Dec 14, 2022

Signed: 


E-Mail: michael.l.dye2.civ@army.mil











WV046-001  
Asset#6638 BLR

