

**CERTIFICATION OF WORK**  
**(To be completed by the Contractor and saved in the Contractor's CMMS)**

**FACID/Building:** NY-024 Building: #356

**Date of Visit:** 2/5/23

**Contractor Personnel on Site:**

1. Joseph Benedetto/Fahrenheit Inc.

**CSS:** #91366--WO#-20601

**Service Order:** Yes

**Corrective Maintenance:**

**Service Order Work Performed:**

**Unit:** Ruptured Coil for air handler feeding downstairs office area

**Manufacturer:** Trane

**Model#:** CLCH-SVX07C-EN

**Serial#:** U12C28396

**Description:** Removed ruptured heating coil out of air handler brazed all damaged splits in coil re-assembled as per approved proposal submitted Feb-09-23

**Repairs:** repaired damaged coil and re-installed

To be signed by the Contractor: Print Name: **Joseph Benedetto**

Date: 11/13/2022

Signed: **Joseph Benedetto**

To be signed by Facility Manager: I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed: Print Name/Rank: Vincent Geordano

Date: 02/07/23

Signed: Vincent J Giordano

E-Mail: vincent.j.giordano.ctr@army.mil