

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: USARC Kingwood Date of Visit: 8-7-23

Contractor Personnel on Site:

1. <u>Sam Fisher</u>	4. _____
2. _____	5. _____
3. _____	6. _____

**Service Call Number**

CSS# 91854 WO# 12311

**Description of Repairs**

Work on backflow preventer. Backflow preventer test cock is broken and needs replaced.

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Sam Fisher Date: 8-7-23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Mr. Hufford, Travis Gs-09 Date: August 07 2023

Signed: 

E-Mail: travis.a.hufford.civ@army.mil

1-12-08

Glycol Fed  
Installed

11"  
D.R. 975XL  
W042 898

10-31-07  
Faded  
Broken  
Test  
cock