



Date: 3/3/2023

Region: 4A
FAC ID: PA027

CSS No.: 91968
Maximo Work Order No.: 12067

Asset #: NA

Original Work Request:

There are three Mitsubishi mini splits located in the supply area of the building – There is mold on the fins of the evaporator in rooms 139, 140 and 141. They need to have the evaporators deep cleaned and the blower motors cleaned inside the evaporator part of the mini split. The Soldier in room 140 has a bad cough and is getting sick from this situation with the mold on the evaporator unit.

Description of Repairs Needed:

Labor and material to a.) deep clean the evaporators in rooms, 139, 140 and 141. b.) pull condensate pan and blower assembled from evaporator in rooms 139, 140, 141. c.) deep clean them inside and out.

Material List:

(11) Drain pan Treatment Tablets

Equipment List:

NA

PM WO History:


NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
10	\$1,582.64	\$0.00	\$1,582.64


20230208_124147
02/08/2023 01:23 PM

1708c81d-83af-49cb-8b10-43c458263be8.jpg




20230208_112614
02/08/2023 01:23 PM

b6b3066b-26d8-462c-a2d7-fb41d1e19414.jpg



20230208_120557
02/08/2023 01:23 PM

ca79c09d-f504-4668-b9b1-ff9a2fe78f10.jpg




20230208_130216
02/08/2023 01:23 PM

ff109b83-07b9-45aa-9e65-d6a973d37a64.jpg




20230208_111413
02/08/2023 01:23 PM

9731bcd8-fd65-4381-8ac1-7ea3f9f7f2bf.jpg



20230208_103556
02/08/2023 01:23 PM

1f42e34f-9615-44d4-b5dc-812b7b0b25a7.jpg



20230208_105001
02/08/2023 01:23 PM

790234d6-8e3e-4226-b80e-b5be7478948e.jpg

