

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY067 Date of Visit: 4/28/23

Contractor Personnel on Site:

1. Andrew Henold
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Service Call Number

CSS# 92891 21754  
WO# \_\_\_\_\_

Description of Repairs

Roof leaks and stained ceiling tiles.

---

---

---

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Andrew Henold Date: 5/3/23

Signed: Andrew J. Henold

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Noah Ingreson AFOS Date: 5/5/2023

Signed: [Signature]

E-Mail: \_\_\_\_\_