

Additional Funding Request

NY127	CSS# 93006 WO# 21796		
Description of Repairs	Labor and material to a.) remove the existing faucet, the water line that is leaking is part of it , and install a new faucet hook up all the new water lines and test for proper operation		
Diagnosis: Initial Work Order	Repair cold water line in break room sink. it is leaking		
Diagnostic Fee	NA		
Additional Labor Cost to Perform Repairs	(5) hours x 80.00 = \$400.00		
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%;"> <tr> <td style="width: 60%;">Materials (See attached detail)</td> <td style="width: 40%;">\$226.80</td> </tr> </table>	Materials (See attached detail)	\$226.80
Materials (See attached detail)	\$226.80		
Total Cost of Repair	\$ 626.80		

patrick would like to

share their cart with you

[View Cart](#)

patrick's Cart

Item	In Store	Qty	Item Total
 MOEN Kaden Single-Handle Pull-Down Sprayer Kitchen Faucet with Reflex and Power Clean in Spot Resist Stainless Model #87966SRS Store SKU #1001471969	 Aisle Bay	1	\$189.00
<hr/>			
Subtotal			\$189.00
Shipping			\$0
Sales Tax			\$0
Est. Total			\$189.00



