

Additional Funding Request

NY051	CSS# 93350 WO# 22140							
Description of Repairs	Labor and material to a.) unwire and remove the nonfunctioning exit signs and install new exit signs and rewire and test for proper operation							
Diagnosis: Initial Work Order	There are 3 emergency exit lights not working properly in the USARC. There is also an emergency light not working in the unit storage area of the building.							
Diagnostic Fee	NA							
Additional Labor Cost to Perform Repairs	6 hours x \$80 = \$480.00							
Additional Material Cost to Perform Repairs	<table border="1"><tr><td>Materials (See attached detail)</td><td>NA</td><td>\$1,512.46</td><td>\$1,512.46</td></tr></table>				Materials (See attached detail)	NA	\$1,512.46	\$1,512.46
Materials (See attached detail)	NA	\$1,512.46	\$1,512.46					
Total Cost of Repair	\$ 1992.46							



Cart

Order Summary

Subtotal

\$1,267.88

Estimated Tax

N/A

Estimated Shipping

FREE

Estimated Total

\$1,267.88

As a Red Pass Plus member, you're getting FREE standard shipping on this order.

RED PASS PLUS



LITHONIA LIGHTING

Exit Sign: Emergency Battery Backup, LED, Black, Red, 2 Faces, Ceiling, Nickel Cadmium, 120/277 V AC

Item # 4WT17

Availability

Expected to arrive Tue. May 30.

Qty

4

Your Price

\$316.97 / each

Total \$1,267.88

Products You Have Recently Viewed

LITHONIA LIGHTING

Exit Sign: Emergency Battery Backup, LED, Blac...

Item # 4WT17

Your Price

\$316.97 / each

Qty

1

Add to Cart

LITHONIA LIGHTING

Exit Sign: Emergency Battery Backup, LED, Black...

Item # 4WT13

Your Price

\$276.75 / each

Qty

1

Add to Cart

COOPER LIGHTING

Exit Sign: Emergency Battery Backup, LED, Black...

Item # 16U372

Your Price

\$218.29 / each

Qty

1

Add to Cart

INGERSOLL RAND

Element Filter 10 Micron: Fits Ingersoll Rand Brand

Item # 33NV47

Your Price

\$89.52 / each

Qty

1

Add to Cart

INGERSOLL RAND

Compressor Oil Coolant: 1 L, Bottle, 128 Viscosity...

Item # 2YY83

Your Price

\$27.09 / each

Qty

1

Add to Cart

EXIT