

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039 Date of Visit: 7/12/23

Contractor Personnel on Site:

- | | |
|-----------------------|----------|
| 1. <u>Andy Hunold</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 93602 WO# 22706

Description of Repairs

Repair/ replace two exit lights and 4 emergency lights in
_____ building 3.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Andrew Hunold Date: 7/12/23

Signed: Andrew Hunold

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: COL Forrester Date: 20230712

Signed: [Signature]

E-Mail: _____

EXIT









EXIT



EXIT

The image shows a red rectangular sign with the word "EXIT" in white capital letters. The sign is mounted on a wall made of light-colored corrugated metal. Above the sign, a black cable runs horizontally and then turns upwards. To the right of the sign, several grey plastic cable management components are visible, including a small box and a larger bracket. Multiple grey cables run vertically down the wall, bundled together and secured by a metal crossbar. A dark door frame is visible at the bottom of the image.





