

Date: 8/24/2023

Region: 4A
FAC ID: NY126

CSS No.: 94196
Maximo WO No.: 13417

Asset #: NA

Priority: Urgent



Original Work Request:

Lockset on electrical room door on OMS building does not function. The door will not unlock, therefore cannot be opened. This room contains the all the panel box's for the OMS as well as the fire alarm panel.

Description of Repairs Needed:

Labor and material to a.) repair/ replace lock on electrical room of OMS building with a Corbin Russwin ML20906 LL Mortise lock With solenoid.

Labor:	Labor Hrs	Labor Rate	Total
Technician	12	\$ 100.00	\$ 1,200.00
			\$ -

Material List:	Quantity	Cost	Total
Corbin Russwin ML20906 LL Mortise lock With solenoid.)	1	\$ 482.00	\$ 482.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,200.00	\$482.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,682.00	\$201.84	\$100.92	\$1,984.76

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee

6625 Selmick Dr., Suite A

Elkridge, MD 21075

ESTIMATE**8/23/23**

Quantity	Description	Amount
1	CSS 94146, WO ?, NY126 Repair/ replace lock on electrical room of OMS building. Material: (\$482 Corbin Russwin ML20906 LL Mortise lock With solenoid.) Labor: (12 hours @ \$100/ hr.) \$1200	1682.00
Sub total		1682.00
Sales Tax		N/A
Total		1682.00

Signature_____ Date_____

Signature_____ Date_____





