

CSS 94786

Region 4A

Zone 1

FAC ID: PA209

POC: (AFOS) Cindy Croyle 412-477-7816 (RFOS) Scott Kawska 814-392-6879

Priority- Routine

Description of Repair: Repair the hot water tank as it is leaking at the bottom of the tank from the condensate drain pipe. See attached picture.

-Type of Funding: (COR input)

-Paying Activity Code: (COR input)

-Date & Time: 8/10/2023 0800 hours

-Associated Asset ID: PA209





