

Date: 11/17/2023

Region: 4C  
FAC ID: WV009

CSS No.: 94930  
Maximo WO No.: 14492

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair water fountain in work bay floor, could be clogged filter, bottle filler line barely supplying any water.

**Description of Repairs Needed:**

Labor and material to a.) replace the Elkay Solenoid Valve - 24V and test for proper operation

Labor	Labor Hrs	Labor Rate	Total
Technician	4	\$ 100.00	\$ 400.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
Elkay Solenoid Valve - 24V	1	\$ 110.92	\$ 110.92

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 400.00	\$110.92	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$510.92	--	--	\$510.92

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.  
6625 Selkirk Drive, Suite A  
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.  
5285 Shawnee Road Suite 510  
Alexandria, VA 22312-2334

Date: 11/17/2023 CSS #: 94930  
FAC ID: WV009 WO #: 14492

DESCRIPTION OF WORK			
Labor and material to a.) replace the Elkay Solenoid Valve - 24V and test for proper operation			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	4	\$100.00	\$400.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Elkay Solenoid Valve - 24V	1	\$110.92	\$110.92
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$400.00
	MATERIAL TOTAL		\$110.92
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			<b>\$510.92</b>

Accepted By: \_\_\_\_\_

Date: \_\_\_\_\_

Robertshaw  
ELKAY  
S-45PGN61  
K-78673  
1000001622  
24V 60Hz 7W  
RU US  
C T1  
MEXICO  
173C18

