

Date: 2/16/2024

Region: 4C  
FAC ID: WV010

CSS No.: 96761  
Maximo WO No.: 15190

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair urinal that's leaking and drain needs snaked. Water is all over the floor.

**Description of Repairs Needed:**

Labor and material to a.) snake the drain using a (Milwaukee Snake Auger) b.) replace the rubber O-Ring to prevent leak.

Labor	Labor Hrs	Labor Rate	Total
Technician	4	\$ 100.00	\$ 400.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
Rubber O-Ring	1	\$ 6.67	\$ 6.67

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 400.00	\$ 6.67	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$406.67	--	--	\$406.67

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.  
6625 Selknick Drive, Suite A  
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.  
5285 Shawnee Road Suite 510  
Alexandria, VA 22312-2334

Date: 2/16/2024 CSS #: 96791  
FAC ID: WV010 WO #: 15190

DESCRIPTION OF WORK			
Labor and material to a.) snake the drain using a (Milwaukee Snake Auger) b.) replace the rubber O-Ring to prevent leak.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	4	\$100.00	\$400.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Rubber O-Ring	1	\$6.67	\$6.67
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$400.00
	MATERIAL TOTAL		\$6.67
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			<b>\$406.67</b>

Accepted By: \_\_\_\_\_

Date: \_\_\_\_\_