

Date: 9/30/2024

Region: 4A

CSS No.: 98453

FAC ID: NY030

Maximo WO No.: 16351

Asset #: NA

Priority: Routine



Original Work Request:

Check drain pans on ceiling coil unit on first and second floor. Two offices on second floor had water leaking out of coil units. It was discovered that the large drain pan was tilted away from the drain tube.

Description of Repairs Needed:

Labor and material to a.) check level and clean drains on 22 ceiling air conditioning units, b.) properly dispose of all spent materials at job site.

Labor:

	Labor Hrs	Labor Rate	Total
Service Technician	16	\$ 100.00	\$ 1,600.00
			\$ -

Material List:

	Quantity	Cost	Total
Cleaning materials	1	\$ 20.00	\$ 20.00
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,600.00	\$ 20.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,620.00	\$194.40	\$97.20	\$1,911.60

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: Julie Pape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
9/30/24

Quantity	Description	Amount
1	CSS 98453, NY030 Horseheads, NY WO16351 Check level and clean drains on 22 ceiling air conditioning units. Material: (\$20) Labor: (16 hours @ \$100/ hr.) = \$1600	1620.00
		Sub total 1620.00
		Sales Tax N/A
		Total 1620.00

Signature _____ Date _____

Signature _____ Date _____