

Date: 9/17/2024

Region: 4A

CSS No.: 98984

FAC ID: NY070

Maximo WO No.: 16659

Asset #: NA

Priority: Urgent



Original Work Request:

Repair garbage disposal in breakroom sink. Garbage disposal in 1st floor breakroom is not working. Checked breaker to confirm power. Breaker was not tripped.
Badger 1/2 hp
model 5-84 s/n 13102069994
The sink is not draining properly and standing water starting to smell.

Description of Repairs Needed:

Labor and material to a.) remove bad disposal, b.) supply and install new garbage disposal in first floor breakroom sink, c.) test for proper operation, d.) clean area and properly dispose of all spent materials.

Labor:

	Labor Hrs	Labor Rate	Total
Technician	7	\$ 100.00	\$ 700.00
			\$ -

Material List:

	Quantity	Cost	Total
Garbage disposal	1	\$ 139.00	\$ 139.00
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 700.00	\$ 139.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$839.00	\$100.68	\$50.34	\$990.02

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: Julie Pape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
9/16/23

Quantity	Description	Amount
1	CSS 98984, WO 16659, NY070 Webster, NY Repair garbage disposal in first floor breakroom sink. Material: (\$139) Labor: (7 hours @ \$100/ hr.) = \$700	839.00
		Sub total 839.00
		Sales Tax N/A
		Total 839.00

Signature _____ Date _____

Signature _____ Date _____