

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Repair water fountain by replacing water filter. Technician found that there isn't a water filter in the water fountain. Requested that a water filter be added to unit. There is no room to place in the unit, so would need to be attached to wall beside the unit.

Description of Repairs Needed:

Labor and material to a.) provide and mount (1) 3M water filtration system on wall beside water fountain in main lobby, b.) connect water filtration system to water fountain, c.) Clean up and properly dispose of all debris generated at job site.

Labor	Labor Hrs	Labor Rate	Total
Technician	10	\$ 100.00	\$ 1,000.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
3M Water filtration system 0.5 micron, 1.5 gpm, 3/8", NPT 23NY88	1	\$ 420.36	\$ 420.36
Tube stock 1/4" inside Dia, 3/8" outside Dia, 6ft 60DK48	2	\$ 21.90	\$ 43.80
Elbow, push-to-connect 3/8" x 3/8" Tube OD	2	\$ 17.53	\$ 35.06
Reducing coupling, push to connect 1/2" x 3/8" in Tube OD	2	\$ 18.70	\$ 37.40
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$1,000.00	\$536.62	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,536.62	--	--	\$1,536.62

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 10/31/2024 CSS #: 99081
FAC ID: NY010 WO #: 16881

DESCRIPTION OF WORK			
Labor and material to a.) provide and mount (1) 3M water filtration system on wall beside water fountain in main lobby, b.) connect water filtration system to water fountain, c.) Clean up and properly dispose of all debris generated at job site.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	10	\$100.00	\$1,000.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
3M Water filtration system 0.5 micron, 1.5 gpm, 3/8", NPT 23NY88	1	\$420.36	\$420.36
Tube stock 1/4" inside Dia, 3/8" outside Dia, 6ft 60DK48	2	\$21.90	\$43.80
Elbow, push-to-connect 3/8" x 3/8" Tube OD	2	\$17.53	\$35.06
Reducing coupling, push to connect 1/2" x 3/8" in Tube OD	2	\$18.70	\$37.40
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$1,000.00
	MATERIAL TOTAL		\$536.62
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$1,536.62

Accepted By: _____

Date: _____