

Date: 3/21/2025

Region: 4C  
FAC ID: WV029

CSS No.: 99085  
Maximo WO No.: 17049

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair exit signs, emergency lights and exhaust hose in OMS. Of course, once electricity has been restored to WV029.

**Description of Repairs Needed:**

Tidewater Technician's investigation found that all the exit signs and emergency lights are working. Labor and material to a.) provide and attach new stainless steel exhaust nozzle for 6" extraction hose & clamp, b.) test for proper operation, c.) Clean up and properly dispose of all spent materials.

| Labor                | Labor Hrs | Labor Rate | Total     |
|----------------------|-----------|------------|-----------|
| Tidewater Technician | 4         | \$ 100.00  | \$ 400.00 |
|                      |           | \$ -       | \$ -      |

| Material List:                                      | Quantity | Cost      | Total     |
|---|----------|-----------|-----------|
| Spring Dampered Vertical Stack Adapter TPA-06-06-SS | 1        | \$ 514.64 | \$ 514.64 |
| 6" Hose clamp Stainless steel band 3/4" width 1XGX3 | 1        | \$ 16.35  | \$ 16.35  |
|   |          | \$ -      | \$ -      |
|   |          | \$ -      | \$ -      |
|   |          | \$ -      | \$ -      |
|   |          | \$ -      | \$ -      |

| Equipment List: | Quantity | Cost | Total |
|-----------------|----------|------|-------|
|                 |          | \$ - | \$ -  |
|                 |          | \$ - | \$ -  |
|                 |          | \$ - | \$ -  |

**PM WO History:**

NA

**Estimate Summary:**

| Labor    | Material | Equipment |
|----------|----------|-----------|
| \$400.00 | \$530.99 | \$0.00    |

| Sub Total | G&A 12% | Fee 6% | Total Estimate |
|-----------|---------|--------|----------------|
| \$930.99  | --      | --     | \$930.99       |

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.  
6625 Selkirk Drive, Suite A  
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.  
5285 Shawnee Road Suite 510  
Alexandria, VA 22312-2334

Date: 3/21/2025 CSS #: 99085  
FAC ID: WV029 WO #: 17049

| DESCRIPTION OF WORK  |  |  |  |
|--|--|--|--|
| Tidewater Technician's investigation found that all the exit signs and emergency lights are working.<br>Labor and material to a.) provide and attach new stainless steel exhaust nozzle for 6" extraction hose & clamp, b.) test for proper operation, c.) Clean up and properly dispose of all spent materials. |  |  |  |

| LABOR   | QTY             | UNIT/RATE | TOTAL    |
|---|-----------------|-----------|----------|
| Tidewater Technician                                | 4               | \$100.00  | \$400.00 |
|   |                 | \$0.00    | \$0.00   |
| MATERIAL  | QTY             | UNIT/RATE | TOTAL    |
| Spring Dampered Vertical Stack Adapter TPA-06-06-SS | 1               | \$514.64  | \$514.64 |
| 6" Hose clamp Stainless steel band 3/4" width 1XGX3 | 1               | \$16.35   | \$16.35  |
|   |                 | \$0.00    | \$0.00   |
|   |                 | \$0.00    | \$0.00   |
|   |                 | \$0.00    | \$0.00   |
|   |                 | \$0.00    | \$0.00   |
| EQUIPMENT   | QTY             | UNIT/RATE | TOTAL    |
|   |                 | \$0.00    | \$0.00   |
|   |                 | \$0.00    | \$0.00   |
|   |                 | \$0.00    | \$0.00   |
| SUB-TOTAL COSTS:                                    | LABOR TOTAL     |           | \$400.00 |
|   | MATERIAL TOTAL  |           | \$530.99 |
|   | EQUIPMENT TOTAL |           | \$0.00   |
| TOTAL COST:   |                 |           | \$930.99 |

Accepted By: \_\_\_\_\_

Date: \_\_\_\_\_

